# Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: Cherry Creek Compressor Station

Field Name: N/A Well File #:

Date Incident: 4/6/2015 Time Incident: 16:00 Facility ID Number:

County: MCKENZIE Twp: 149 Rng: 99 Sec: 10 Qtr: SE NE

Location Description:

Submitted By: Jason Henry Received By:

Contact Person: Jason Henry

3015 16th Street SW, Suite 20

Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.2 MileDistance Nearest Water Well:0.2 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spilled	Units	Recovered	Units	
Oil	0.8	Barrels	0.5	Barrels	
Rrino	0.8	Rarrole	0.5	Rarrole	

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

### Risk Evaluation:

The station piping has been isolated and depressurized until repairs can be made.

#### Areal Extent:

N/A - the release remained within the boundary of the facility.

Followup

Units

# Potential Environmental Impacts:

The extent of the impacted soil will be further evaluated when the station piping is excavated for repair work.

#### Action Taken or Planned:

The station piping will be repaired, and any impacted soil that is encountered during the repair work will be transported off-site for proper disposal.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

## **Updates**

Date: 4/9/2015 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release due to pipeline leak at compressor station. Followup is necessary.

Date: 4/13/2015 Status: Inspection Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

On site 4/13/2015, at 5:20 p.m. Leak was from pipeline behind main building on location. Vac truck was on site and sucked up as much of liquid as possible. Some backfilling has taken place with the remainder being done this week. Release remained on site. No further followup required at this time.